

## ADHESIVE SILICONE PAD HEATERS

### IMPORTANT SAFETY MESSAGE



- Attach heater to metal surface only!
- Surface must be flat and smooth, no bumps, ridges, or grooves
- Surface must be warmed to >100°F (38°C)
- Do not use additional adhesives to secure heater



### PREPERATION

1. Select area to adhere on a metal surface to assure full coverage over entire pad
2. Clean selected area. Remove any dirt, grease, oil. (Step #2)
3. Remove all paint from the selected area slightly larger than the heater. Finish with a scuffed area using sandpaper. Do not polish. (Step #4)
4. Use acetone or brake cleaner to wipe the area clean. Do not use gasoline, solvents, spray penetrants, diesel fuel or any other product that leaves a film. Wipe heater area completely dry. (Step #4)

